Approved For Release 2003 CLASSIFICATION	SECRITA			प्र
COUNTRY Soviet Some of Germany		REPORT_NO	05V4 ·	
TOPIC Staaken Airfield		A CONTRACTOR OF THE PROPERTY O	25X1	
EVALUATION 25X1 PLAC	E OBTAINED		-	
DATE OF CONTENT 97 January to 10	February 19	₅₀ 25X1		
DATE OBTAINED	DATE_PREPA	ARED 29 March 1	950	
REFERENCES	25X1			
PAGES 3 ENCLOSURES (NO. & TYPE	E)		na a tradicipa. In 1985 militar de la companya del companya de la companya de la companya del companya de la co	Franchista de Arthury, and a regag
REMARKS		× ×	Matter militari e septembro e de Proposition de La come e d	
1617/0110		омення при	-	
The Control of Control of the Control of Con	-			25X

25X1


1. On 27 January 1950 nine green twin-engine low-wing monoplanes with single rudder assembly and white figures and another plane with silver sheen were parked in front of the flight control station of the Staaken (N 53/Z 65) airfield. The yellow lateral stripe previously seen on the rudder assembly was not noticed. A twin-engine low-wing monoplane made continual local flights between 2 and 2 p.m. in cloudless but hazy weather. During the flying the plane occasionally taxied to the northern edge of the field where some tank trucks and other motor vehicles were parked, or it zoomed off without landing though being close above the ground.

25X1

- 2. There was flying with two biplanes, two high-wing monoplanes and two twin-engine low-wing monoplanes with single rudder assembly between 11 a.m. and 1 p.m. on 3 February 1950 in cloudless weather and a 4-km visibility range.
 - a. Eight to ten twin-engine low-wing monoplanes with red propeller hubs, one with a silver sheen and the other in color, were parked in front of the flight control station.
 - b. The first twin-engine low-wing monoplane with the figure 7 on the rudder assembly, seven windows and a door at the right side, took off at 11 a.m. Shortly afterwards the second plane with the figure 10 on the rudder assembly and the following distinguishing features took off:

Six windows and a door at the left side and two white quadrilaterals painted on the rudder assembly, one above the other. The planes stayed in the air for 15 to 20 minutes. The two biplanes, U-2s, which had a two-man crew, and tandem seats, made local flights.

CONFIDENTIAL



in front of the flight control station on 10 February 1950. The planes made local flights between 12:30 and 2 p.m. A silver craft of the same type was boarded by 15 to 20 men, taxied to the eastern edge of the field, took off and, shortly after lifting off the ground, touched ground again and taxied along the field beyond its border far into the adjacent fields. It then taxied back to the take-off point and, after the landing gear was checked, took off without difficulties about 1:30 p.m. heading west-southwest. The plane had seven windows at the left side, six windows and a door at the right side, and a red figure on the rudder assembly. 4. The E-W runway was marked by 24 branches, about 50 meters apart, stuck into the ground.		SECRLT	25X1
cockpit under wings, box-like fuselage, cockpit sloping to the rear, leading adge of wing notched over ockpit, lending gear in line with leading edge of wings. The planes took off from west to east. Several tenk trucks, an ambulance and two trucks were standing at the teke-off point. 25X1 25			
cockpit under wings, box-like fuselage, cockpit sloping to the rear, leading adge of wing notched over ockpit, lending gear in line with leading edge of wings. The planes took off from west to east. Several tenk trucks, an ambulance and two trucks were standing at the teke-off point. 25X1 25			
in front of the flight control station on 10 February 1950. The planes made local flights between 12:30 and 2 p.m. A silver craft of the same type was boarded by 15 to 20 men, taxied to the eastern edge of the field, took off and, shortly after lifting off the ground, touched ground again and taxied along the field beyond its border far into the adjacent fields. It then taxied back to the take-off point and, after the lending gear was checked, took off without difficulties about 1:30 p.m. heading west-southwest. The plane had seven windows at the left side, six windows and a door at the right side, and a red figure on the rudder assembly. 4. The E-W runway was marked by 24 branches, about 50 maters apart, stuck into the ground. 5. On 10 February 1950 six twin-engine DC-3 transports with red propeller hubs and a stripe about 10x40 centimeters on the novable section of the rudder assembly, were perked in front of the closed bengars of the field. The planes made flights in the morning at long intervals. They climbed to an actitude of about 1,000 meters, headed westward, returned 30 to 35 minutes leter, made a landing approach and zoomed upper again. This was repeated. (This information was verified by the observation of the figures on the planes.) During flying, soldiers moved between the two redo stations west of the field. Local flights were practiced in connection with radio concumication. 6. Two 2C-5s without paint landed at the field and parked in front of the hangars. A high-wing monoplane with glazed cock, it, conspicuously high landing gear and in-line engine was also parked there. The field dump on the northern edge of the field was strictly guarded. The field railroad spur track was rusty. Comment: a. Comment:		cockpit under wings, box-like fuselage, cockpit sloping to the rear, leading edge of wing notched over cockpit, lending gear in line with leading edge of wings. The planes took off from west to east. Several tank trucks, an ambulance and two trucks were standing at the take-off	25X1
5. Cn 10 February 1950 six twin-engine DC-3 transports with red propeller hubs and a stripe about 10x40 centimeters on the novable section of the rudder assembly, were parked in front of the closed hengars of the field. The planes made flights in the morning at long intervals. They climbed to an a.titude of about 1,000 meters, headed westward, returned 30 to 35 minutes later, made a landing approach and zoomed upward again. This was repeated. (This information was verified by the observation of the figures on the planes.) During flying, soldiers moved between the two radio stations west of the field. Local flights were practiced in connection with radio communication. 6. Two NC-3s without paint landed at the field and parked in front of the hangars. A high-wing monoplane with glazed cock, it, conspicuously high landing gear and in-line engine was also parked there. The fuel dump on the northern edge of the field was strictly guarded. The field railroad spur track was rusty. Comment: a	3 _{•.}	in front of the flight control station on 10 February 1950. The planes made local flights between 12:30 and 2 p.m. A silver craft of the same type was boarded by 15 to 20 men, taxied to the eastern edge of the field, took off and, shortly after lifting off the ground, touched ground again and taxied along the field beyond its border far into the adjacent fields. It then taxied back to the take-off point and, after the landing gear was checked, took off without difficulties about 1:30 p.m. heading west-southwest. The plane had seven windows at the left side, six windows and a door at the right side, and a red figure on the rudder	
red propeller hubs and a stripe about 10x40 centimeters on the novable section of the rudder assembly, were parked in front of the closed hengars of the field. The planes made flights in the morning at long intervals. They climbed to an altitude of about 1,000 meters, headed westward, returned 30 to 35 minutes later, made a landing approach and zoomed upward again. This was repeated. (This information was verified by the observation of the figures on the planes.) During flying, soldiers moved between the two radio stations wast of the field. Local flights were practiced in connection with radio communication. 6. Two 2C-3s without paint landed at the field and parked in front of the hangars. A high-wing monoplane with glazed cock, it, conspicuously high landing gear and in-line engine was also parked there. The fuel dump on the northern edge of the field was strictly guarded. The field railroad spur track was rusty. Comment: A high-wing monoplane with glazed Comment Commen	4.	The E-W runway was marked by 24 branches, about 50 meters apart, stuck into the ground.	
front of the hangers. A high-wing monoplane with glazed cock, it, conspicuously high landing gear and in-line engine was also parked there. The fuel dump on the northern edge of the field was strictly guarded. The field railroad spur track was rusty. 25X1 Comment: a. the field was occupied by	5°	red propeller hubs and a stripe about 10x40 centimeters on the novable section of the rudder assembly, were parked in front of the closed hangars of the field. The planes made flights in the morning at long intervals. They climbed to an altitude of about 1,000 meters, headed westward, returned 30 to 35 minutes later, made a landing approach and zoomed upward again. This was repeated. (This information was verified by the observation of the figures on the planes.) During flying, soldiers moved between the two radio stations west of the field. Local flights were practiced	
a. the field was occupied by	6.	front of the hangars. A high-wing monoplane with glazed cock, it, conspicuously high landing gear and in-line engine was also parked there. The fuel dump on the northern edge of the field was strictly guarded. The field	25X1
a. the field was occupied by			
a. the field was occupied by		Comment:	
SECRET 25X1		the off old was convited by	
		SECULT.	25X1

25X1

25X1

25X1

25X1

Approved For Release 2003/08/11: CIA-RDP82-00457R004700370010-6

CONFIDENTIAL

SECRET		25X1
	0	

twin-engine aircraft, some FO-2s and some high-wing monoplanes. According to previous information, the twin-engine aircraft are assigned to a transport unit . The unit was previously stationed in Schoenwalde.

25X1

b. The twin-engine planes are, according to the given description, LI-2s. The planes with the doorf on the left side are possibly Yak-16s and the high-wing monoplanes Yak-14s.

SECHET	25X ²